

SP-SPARK PLUGS

SP

**ELECTRICAL
SECTION**

AA

**BRAND
OR
DESCRIPTION**

000

**PART
NUMBER**

Spark Plugs Nippon Denso
Spark Plugs NGK
Spark Plug Caps
Spark Plug Leads
Spark Plug Lead Connectors
TCI Moduels Yamaha KT100S
TCI Moduel Brackets
Spark Plug Reading Chart

Page SP-3
Page SP-3
Page SP-3
Page SP-3
Page SP-3
Page SP-5
Page SP-5
Page SP-2

FIRING END ANALYSIS



NORMAL

Insulator nose has slight deposits. Colour ranges from brown to greyish-white. Spark plug is functioning correctly under good engine conditions.




INSULATOR BREAKAGE

The insulator nose is cracked or split. Breakage not resulting from mechanical impact is caused by sudden heating or cooling (thermal shock). Severe detonation will often produce the type of breakage shown in the picture. Causes of detonation are similar to what is described in "Overheated".



CARBON FOULED

Dry, soft, black carbon deposits form in large quantities on the insulator nose and electrodes. As carbon accumulates the insulation between the centre and ground electrodes deteriorates, an electrical leakage path is formed by the carbon and misfire results. Causes of carbon fouling include; rich fuel mixture, clogged air filter, faulty choke system, prolonged low speed driving or idling, faulty ignition system, over-retarded ignition timing and spark plug heat rating is too cold.



MELTED

The centre and/or ground electrode surface is uneven and cauliflower-like in appearance. The insulator is blistered and possibly contains metallic deposits. Melted firing end results from overheating. Refer to "Overheated" for causes.



OIL FOULED

Wet, black, oily, carbon deposits form on the insulator nose and electrodes. As described in "Carbon Fouled", misfire results due to the reduction in insulation resistance between centre and ground electrodes. Causes of oil fouling include; excessive oil entering into combustion chamber, oil level is too high, worn piston rings, cylinders and valve guides.



ABNORMAL EROSION

The centre and/or ground electrodes are badly worn relative to the length of operation. Misfire will eventually result due to the high ignition voltage needed for the large gap. Abnormal erosion is often caused by harsh lead and oil additives combined with severe operating conditions such as high speed driving.




DEPOSITS (Ash Formation)

Heavy ash deposits build-up on the firing end and eventually cause misfire. In some circumstances these deposits can reach temperatures which might lead to pre-ignition. Ash formation is mainly produced from the burning of oil, type of oil, fuel additives and engine condition.



RAPID ABNORMAL EROSION

The centre and/or ground electrodes are very badly worn. Their surfaces are fretted and rough. The electrodes have oxidized and sometimes turn green when the oxidation is heavy. Rapid abnormal erosion is produced by a more aggressive operating environment than "Abnormal Erosion". Refer "Abnormal Erosion" for causes.



LEAD FOULED

Lead fouling usually appears as yellowish brown deposits on the insulator nose. The lead deposits have no adverse effect on starting, idling or low speed driving but do cause misfire during rapid acceleration or under heavy engine load. Misfire results when the lead deposits become electrically conductive at high temperatures creating a reduction in the insulation resistance between centre and ground electrodes. The lead additives used to enhance the fuel octane rating are the source of lead deposits. Lead fouling will not occur with unleaded fuel.



LEAD EROSION

The ground electrode is badly worn and appears to be chipped. Lead erosion is caused by the harsh lead additives in the fuel. At high temperatures these additives chemically react with the nickel alloy electrodes and separate the grain boundary of the nickel alloy.



OVERHEATED

Overheated spark plugs have a white glazed or glossy insulator. Small black deposits accumulate on the insulator nose and the electrodes are prematurely worn. Causes of overheating include; over-advanced ignition timing, lean fuel mixture, insufficient fuel octane rating, excessive deposits accumulated in combustion chamber, manifold air leak, insufficient cooling and lubricating, spark plug heat rating is too hot.



NORMAL WEAR

The centre and/or ground electrodes are worn. Deposits cover the insulator nose and ground electrode. This plug has operated under normal conditions for a considerable period and reached the end of its life. Further useage will cause misfire, bad fuel economy and poor engine performance.

SPARK PLUGS

NGK SPARK PLUGS



IRITOP 7	Part Number	SP021A
IRITOP 8	Part Number	SP022
IRITOP 9	Part Number	SP003IRIT09

IRIDIUM NGK SPARK PLUGS [suitable for COMER S/W 80]



BR8HIX	Part Number	SP001D1 [same as original]
BPR7HIX	Part Number	SP001C1 [protrusion tip type]
BPR8HIX	Part Number	SP001D [protrusion tip type]

NGK RACING SPARK PLUG



B8EGV	Part Number	SP002
B8.5EGV	Part Number	SP002A
B9EGV	Part Number	SP003
B9.5EGV	Part Number	SP004
B10EGV	Part Number	SP005
B10.5EGV	Part Number	SP005A
B11EGV	Part Number	SP005B

DENSO IRIIDIUM RACING SPARK PLUGS



IW27	Part Number	SP005N
IW29	Part Number	SP005M
IW31	Part Number	SP006

SPARK PLUG CAPS & LEADS




NON RESISTOR NGK CAP
part number **SP011**



5 ohm RESISTOR CAP
same as ROTAX & YAMAHA
part number **SP012**



5 ohm RESISTOR CAP
same as LATE YAMAHA
part number **SP013**



part number



SMALL PVL
[NON RESISTOR TYPE]
part number **SP014A**



R/R
[NON RESISTOR TYPE]
part number **SP014AR/R**



NGK LEAD REPAIR KIT
[includes lead and 5ohm resistor cap]
part number **EPY639**




LEAD JOINER KIT
part number **EPY639A**

YAMAHA KT100S TCI & SUPPORT BRACKET



BILLIT ALLOY BRACKET [GOLD]
EPY638G



PRD/ATOM NON GENUINE TCI
EPY638A



BILLIT ALLOY BRACKET [BLACK]
EPY638H



GENUINE YAMAHA TCI
EPY638

PVL COILS , STATORS and ROTORS ANALOG IGNITION SYSTEM



PVL COIL PRIMARY BULLIT PLUG LEAD
EPGC041



PVL COIL PRIMARY SPADE TERMINALS
EPGC0412



STATOR WITH 90mm SPIGOT
EPGC0412PVL90



STATOR WITH 94mm SPIGOT
EPGC0412PVL



ROTOR with SMALL TAPER
EPGC043PVLS12MM



ROTOR with LARGER TAPER
EPGC043PVL15MM